



RS232 SERIAL CABLE WIRING

RX = RED
 TX = WHITE
 COM = GREEN

RS485 CABLE WIRING

COM = WHITE
 A = GREEN
 B = RED

12 V DC
 WALL CUBE TRANSFORMER
 +12 VDC = White
 0 V = Shield

**To Osborne
 Power Supply**