

**FIRE System Wiring**  
 Feeder: MK3  
 PSU: Osborne PSU  
 Interface: Osborne Interface

9 VOLTS DC 100 mA  
 WALL CUBE TRANSFORMER  
 INSULATED WIRE IS +  
 NON-INSULATED WIRE IS -

**RS485 CABLE WIRING COLORS**

COM	WHITE
A	GREEN
B	RED

**RS232 SERIAL CABLE WIRING COLORS**

RX	RED
TX	WHITE
COM	GREEN

**COMMUNICATION**  
 B RED  
 A GREEN  
 0 V WHITE  
 Connect shield wire to 0 V COM IN only.

**SUGGESTED STATION WIRING COLOR CODE**  
 +24 V dc = BLACK  
 0 V dc = WHITE  
 A = GREEN  
 B = RED  
 SHIELD = BARE

**DETAIL C**

